(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING HAL034013 01/08/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 250 PITT STREET SHULER HEATH CARE/STOREY VILLA KERNERSVILLE, NC 27284 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 000 Initial Comments C 000 This report is of a Biennial Construction Survey done by Bob Getchell on January 8, 2016. This facility was first licensed as a Home for the Aged serving 12 ambulatory residents on January 10, 1980. Therefore the facility must meet the 1977 and the applicable portions of the 2005 Rules for the Licensing of Adult Care Homes, and, the 1978 North Carolina State Building Code Section 409 - Institutional Unrestrained Occupancy. Deficiencies were noted which will require a new plan of correction. C 101 C 101 Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm". copies of which are available at the Division of Health Service Regulation at no cost; This Rule is not met as evidenced by: 1. Based on observation, the building fire

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING: <b>01</b>			(X3) DATE SURVEY COMPLETED		
		HAL034013		B. WING		01/0	08/2016
NAME OF F	PROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, S	STATE, ZIP CODE		
SHULER	HEATH CARE/STORI	EY VILLA	250 PITT	STREET SVILLE, NC	27284		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY F SC IDENTIFYING INFORMAT	ULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETE DATE
C 101	spaces in accordan Code in effect at the would affect all residuativating the fire al from the building.  Findings include: a) The Med room hadetection tied into the b) The corridor bat detection or heat defended.	at was not installed in ce with the NC State etime of construction dents by not detecting arm, and directing results as no smoke detection	Building . This g smoke, sidents on or heat ke re alarm.	C 101			
	fire and building saf shall be maintained review.  This Rule is not me 1. Based on observ not available at the Findings include:	have current sanitation fety inspection reports in the home and avantation as evidenced by: vation, current reports time of the survey.	s which ilable for s were				
C 133	Bathrooms-Hand G SECTION .0300 - F 10A NCAC 13F .030 ENVIRONMENT (e) The requirement rooms are: (6) Hand grips shall	PHYSICAL PLANT 05 PHYSICAL nts for bathrooms and	l toilet	C 133			

Division of Health Service Regulation

STATE FORM 6899 O64F21 If continuation sheet 2 of 7

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		` '			TE SURVEY MPLETED	
HAL034013		B. WING	B. WING		01/08/2016	
NAME OF F	PROVIDER OR SUPPLIER	STREE	T ADDRESS, CITY,	STATE, ZIP CODE		
SHULER	HEATH CARE/STOR	FY VII I A	ITT STREET IERSVILLE, NC	27284		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES  / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF ( (EACH CORRECTIVE ACTI CROSS-REFERENCED TO T DEFICIENC'	ION SHOULD BE HE APPROPRIATE	(X5) COMPLETE DATE
C 133	Continued From pa	ge 2	C 133			
	commodes, tubs ar accessible to reside	nd showers used by or ents;				
		et as evidenced by: vation, the facility was not e manner by having a loose	•			
	Findings Include: The tub bathroom has a loose grab bar at the tub.		tub.			
C 150	O Corridors-Free of equipment and Obstructions		C 150			
			d			
	was not maintained corridors blocked b	et as evidenced by: vation, egress from all area I in a safe manner by havin y furniture. This would affe allowing free egress in an	g			
	end tables extending	is wall-mounted shelves an ig into the corridor reducing ridor to less than 5 feet.				
C 164	Housekeeping and	Furnishings-Clean, Repair	ed C 164			
	FURNISHINGS (a) Adult care home	06 HOUSEKEEPING AN	D			

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPL A. BUILDING:	E CONSTRUCTION  01	TRUCTION (X3) DATE SURVE COMPLETED			
HAL034013		B. WING		01/0	01/08/2016		
NAME OF I	PROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, S	STATE, ZIP CODE		
SHULER HEATH CARE/STOREY VILLA 250 PITT S KERNERS			STREET SVILLE, NC	27284			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY	ON SHOULD BE IE APPROPRIATE	(X5) COMPLETE DATE	
C 164	Continued From page 3  coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities.  This Rule is not met as evidenced by: 1. Based on observation, some building components were not maintained in clean, repaired condition.  Findings include: a) Throughout the building the HVAC return vents and their associated radiation dampers are covered with dust and dirt which could interfere with the damper activating properly in a fire emergency. b) Room 3 has a worn chair. c) Room 6 has a missing handle on the chest of drawers		C 164				
C 166	Housekeeping-Mail SECTION .0300 - F 10A NCAC 13F .03 FURNISHINGS (a) Adult care home (5) be maintained orderly manner, free hazards; (e) This Rule shall facilities.  This Rule is not mail. Based on obsermaintained in a saf of oxygen cylinders residents by potent from a ruptured cylinders.	PHYSICAL PLANT 06 HOUSEKEE es shall: in an uncluttered, e of all obstruction apply to new and et as evidenced by vation, the building e manner by impresentation. This would affectially exposing ther	clean and ns and existing  y: g was not oper storage et all	C 166			

· · · · · · · · · · · · · · · · · · ·		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>		(X3) DATE COMP	SURVEY LETED
HAL034013		B. WING		01/0	01/08/2016	
NAME OF I	PROVIDER OR SUPPLIER			STATE, ZIP CODE		
SHULER	HEATH CARE/STOR	EY VILLA 250 PITT KERNER:	STREET SVILLE, NC	27284		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETE DATE
C 166	Continued From page 4		C 166			
		are being stored in a t can not adequately prevent over.				
C 189	Building Equipment	t Maintained Safe, Operating	C 189			
	SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.					
	maintained in a saf the fire-resistance r	vation, the building was not e manner by not maintaining rating of building components. Il residents by not containing ne room or smoke				
	section of gypsum	vall/ceiling joint separating. unprotected ceiling				
	2. Based on observation, the facility components were not maintained operable by having doors that did not close completely and latch.					

6899

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		· ,	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>		(X3) DATE SURVEY COMPLETED	
HAL034013		B. WING		01/08/2016		
NAME OF F	PROVIDER OR SUPPLIER			STATE, ZIP CODE		
SHULER	HEATH CARE/STOR	EY VILLA KERNERS	STREET SVILLE, NC	27284		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUI CROSS-REFERENCED TO THE APPRO DEFICIENCY)	JLD BE COMPLETE	
C 189	Continued From pa	ge 5	C 189			
	not close and latch b) The right Exit do when released c) The room 4 bed and frame and will i d) Room 3 has a lo e) Storage room do door knob f) Room 2 has a lo g) Room 6 has a d bottom.  3. Based on observ system was not ma safe by allowing rese extension cords and	or will not close and latch room door scrubs the floor not close and latch lose door handle. foor next to the Laundry has no lose door handle loor delaminating at the loor				
	outlets. This would affect all residents by potentially overloading electrical circuits in the bedrooms.  Findings include: Outlet expansion devices were observed in the					
	following locations: a) Room 6 has an outlet expansion device, b) Room 4 has an outlet expansion device, c) Room 2 has an outlet coming out of the wall.					
	4. Based on observation, the building exit signage was not maintained operable.					
	Findings include: a) The Exit sign at the left exit has no battery backup.					
C 199	9 Exhaust Ventilation		C 199			

6899

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING: <b>01</b>		(X3) DATE SURVEY COMPLETED		
HAL034013			B. WING		01/0	8/2016
NAME OF PROVIDER OR SUPPLIER STREET ADD				STATE, ZIP CODE		
SHULER	R HEATH CARE/STORI		STREET SVILLE, NC	27284		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES YMUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROPRIED TO THE APPROPRIED TO THE APPROPRES (CROSS-REFERENCE)	.D BE	(X5) COMPLETE DATE
C 199	SECTION .0300 - F 10A NCAC 13F .03 REQUIREMENTS (g) The spaces list- provided with exhaut two cubic feet per in requirement does in before April 1, 1984 these specified spa (1) soiled linen stor (2) soil utility room; (3) bathrooms and (4) housekeeping of (5) laundry area. (k) This Rule shall facilities with the ex- which shall not app  This Rule is not me 1. Based on observentilation was not this Rule.  Findings include:	PHYSICAL PLANT 11 OTHER  ed in this Paragraph shall be ust ventilation at the rate of ninute per square foot. This tot apply to facilities licensed with natural ventilation in ces: rage;  toilet rooms; closets; and apply to new and existing reption of Paragraph (e) ly to existing facilities.  et as evidenced by: vation, the building exhaust maintained in accordance with	C 199			

6899